

LFC000700

LONGVIEW FIBRE COMPANY

Western Container Division

P.O. Box 24867
Seattle, WA 98124

Phone: (206) 762-7170 FAX: (206) 767-2442

5901 E. Marginal Way S.
Seattle, WA 98134



PLEASE SUBMIT INVOICES IN DUPLICATE
PURCHASE ORDER

THIS NUMBER MUST SHOW ON ALL PACKING
LISTS, INVOICES AND ALL COMMUNICATIONS
CONCERNING THIS ORDER.

REQUISITION NO. 098251	BUYER SLB	TERMS NET 30	SUPPL. #	SE- 704092
NORTHWEST METAL & SALVAGE SERV 9607 AURORA AVE. N. SEATTLE WA 98103 Contact: BRAD RINKER Ph: 206-525-0814 Fax: 206-525-0859			SHIP TO: LONGVIEW FIBRE COMPANY 5901 E. MARGINAL WAY S. SEATTLE WA 98134 Due Date: 5/9/97	

TAX INFORMATION		WASHINGTON PERMIT NO. 084-000-07
TAXABLE		
ORDER STATUS	SHIP VIA	F.O.B. POINT
CONFIRMATION	VENDOR	

REQUIRED AT OUR PLANT NO LATER THAN		Item #	Location/Dept.	Acct Code	Unit Cost	
ITEM	QUANTITY	ITEM DESCRIPTION				PRICE
1	1.00	BOILER DEMOLITION		C3-8000	\$2,800.00	\$2,800.00
NORTHWEST METALS WILL PROVIDE ALL LABOR, MATERIALS AND EQUIPMENT NEEDED TO DEMOLISH AND REMOVE BOILER LOCATED AT COLE INDUSTRIAL (LYNNWOOD, WA) . NORTHWEST METALS HAS ALL SALVAGE RIGHTS TO MATIERALS GENERATED FROM DEMOLITION. NORTHWEST METALS WILL REMOVE DEBRIS GENERATED FROM BOILER DEMOLITION, TRANSPORT IT OFF SITE, AND LEGALLY DISPOSE OF MATERIAL. NORTHWEST METALS WILL LEAVE SITE IN A BROOM CLEAN CONDITION.						
2	1.00	ASBESTOS ABATEMENT			\$1,500.00	\$1,500.00
(NOT TO EXCEED BID)						

Subtotal: \$4,300.00
Tax: \$0.00
Order Total: \$4,300.00


ITEM	QUANTITY RECEIVED	LAST DEL. CARRIER	FRT. BILL NUMBER	P/C	CHECKED BY	DATE	ITEM	QUANTITY RECEIVED	LAST DEL. CARRIER	FRT. BILL NUMBER	P/C	CHECKED BY	DATE
1	1			C	SLB	5/16/97							
2	1												

DATE	DISC.	NOTE	ITEM	QUANTITY	RECEIVED	CLERK	CLEAR	RET.	AC

RECEIVING

LFC000701

MANUFACTURERS' REPRESENTATIVES



Engineered Equipment for the Generation,
Distribution and Utilization of Heat

April 18, 1997

Sonny Bivins
LONGVIEW FIBRE - SEATTLE
5901 E. Marginal Way South
Seattle WA 98134

Subject: DEMO OF LONGVIEW FIBRE 500HP WATERTUBE BOILER

Dear Mr. Bivins:

With reference to the above 500HP watertube currently stored in the Cole Industrial yard, we understand that Longview Fibre is planning to proceed with demolition in the near future and that demolition is to take place in Cole yard. Since asbestos is present, in the form of gasketing between the stack and boiler, as well as around the tubes and joints, we would like to clarify the following abatement and disposal procedures:

1. Containment, removal, and disposal of any and all hazardous materials is the responsibility of Longview Fibre.
2. Longview Fibre is responsible for all crane and freight charges to load out and transport boiler for scrap.


Please confirm your agreement with the above by signing and returning the enclosed copy of this letter.

Thank you.

Sincerely,
COLE INDUSTRIAL, INC.


David E. Cole
Aftermarket Services Dept.

LONGVIEW FIBRE - SEATTLE


Sonny Bivins
Longview Fibre Maintenance Dept.

cc: Tom Craig, Longview Fibre
Glenn Waldenberg, Cole Industrial

\\lab\m:\sh\sr\job\Nlvfibre 106


PORTLAND OFFICE:
6775 S.W. 111th Ave. • Suite 201
Beaverton, OR 97008
(503) 641-6641 • Fax (503) 626-2873

HEADQUARTERS:
Office and Warehouse: 5924 203rd S.W.
Lynnwood, WA 98036
(206) 774-6602 • Fax (206) 775-2272

YAKIMA OFFICE:
624 N. Third Ave.
Yakima, WA 98902
(509) 457-5015 • Fax (509) 457-5160

LFC000702

MANUFACTURERS' REPRESENTATIVES



Engineered Equipment for the Generation,
Distribution and Utilization of Heat

February 5, 1997

Tom Craig, Plant Manager
LONGVIEW FIBRE - SEATTLE
5901 E. Marginal Way South
Seattle WA 98134

Subject: REMOVAL OF LONGVIEW FIBRE 500HP WATERTUBE BOILER

Dear Mr. Craig:

As per our agreement made on November 1, 1995, we have provided 12 months storage in our yard for the 500HP Watertube Boiler which was removed from Longview Fibre's Seattle facility in the fall of 1995.

Our agreement is that if the boiler has not been purchased within the 12-month period, Longview Fibre will be responsible for all crane and freight charges to load out boiler for scrap. (Asbestos removal, if required, is responsibility of Longview Fibre.)

Since there have been no offers for this unit within the past 12 months, we are now requesting a purchase order number so that we may charge crane and freight expense to load out this boiler for scrap. Please work with Casey Beachell in Aftermarket Services to coordinate the above: (206) 774-6602, Ext. 216.

Thank you.

Sincerely,

COLE INDUSTRIAL, INC.

Randy R. Cole
Aftermarket Services Dept.

cc: Sonny Bivins, Longview Fibre
Glenn Waldenberg, Cole Industrial

\\eab\m:\sh\sr\job\llivfibre.105


PORTLAND OFFICE:
6775 S.W. 111th Ave. • Suite 201
Beaverton, OR 97008
(503) 641-6641 • Fax (503) 626-2673

HEADQUARTERS:
Office and Warehouse: 5924 203rd S.W.
Lynnwood, WA 98036
(206) 774-6602 • Fax (206) 775-2272

YAKIMA OFFICE:
624 N. Third Ave.
Yakima, WA 98902
(509) 457-5015 • Fax (509) 457-5160

LFC000703

MANUFACTURERS' REPRESENTATIVES



NOV 16 1995

Engineered Equipment for the Generation,
Distribution and Utilization of Heat

November 2, 1995

Tom Craig, Plant Manager
LONGVIEW FIBRE - SEATTLE
5901 E. Marginal Way South
Seattle WA 98134

**Subject: REMOVAL & STORAGE OF LONGVIEW FIBRE'S
500HP WATERTUBE BOILER**

Dear Mr. Craig:

With this letter we would like to confirm our understanding as regards your existing boiler. Our intent is to insure that all parties are in agreement with the arrangement we discussed at our meeting yesterday, Nov. 1, 1995.

Cole Industrial, Inc. will provide 12 month's storage while unit is offered for sale on a consignment basis.

Longview Fibre will be responsible for crane charges to load out boiler at jobsite and unload boiler at Cole Industrial's yard in Lynnwood, WA. Longview Fibre will also pay all freight charges to bring unit to Cole's yard.

In the event the boiler is not purchased within the 12 month period, Longview Fibre will be responsible for all crane and freight charges to load out boiler for scrap. Asbestos removal, if required, will be your responsibility.

Please confirm your understanding and agreement to the above by signing and returning a copy of this letter (enclosed).

Sincerely,
COLE INDUSTRIAL, INC.

Randy R. Cole, Aftermarket Services

LONGVIEW FIBRE

Tom Craig, Plant Manager

cc: Sonny Byrns, Longview Fibre
Glenn Waldenberg, Cole Industrial

\\lab\m:\sh\sr\job\W\Fibre.101

PORTLAND OFFICE:
6775 S.W. 111th Ave. • Suite 201
Beaverton, OR 97008
(503) 641-6641 • Fax (503) 626-2673

HEADQUARTERS:
P.O. Box 1336 • Lynnwood, WA 98046
(206) 774-6502 • Fax (206) 775-2272
Office and Warehouse: 5924 203rd S.W.

YAKIMA OFFICE:
P.O. Box 10123
Yakima, WA 98909
(509) 457-5015 • Fax (509) 457-5160

LFC000704